

NOTES:
1. SYMBOLS ARE ELECTRICAL REPRESENTATION ONLY.
2. TO BE WIRED IN ACCORDANCE WITH NATIONAL ELECTRIC N.E.C. AND LOCAL CODES.
3. USE COPPER CONDUCTORS ONLY. USE COPPER WIRE ONLY, RATED 70° C OR HIGHER
   ◇ UTILISEZ DES FILS EN CUIVRE SEULEMENT, CLASSE 75°C OU PLUS.
4. CHECK ALL ELECTRICAL CONNECTIONS INSIDE CONTROL BOX FOR TIGHTNESS.

REFERENCE WIRING HARNESS
2892, 2894, 3253, & 3254

ICE ENERGY®
INTELLIGENT STORAGE AT WORK.™

Ice Bear® 30 Unit
CoolData® Controller Electrical Schematic
for 208/230V 1Ph Applications
Ref. # 3256 Rev C